

LOW THERMAL MASS HEATED FUSER

Roland Boss

10007748-1

1/3




FIG. 1

LOW THERMAL MASS HEATED FUSER

Roland Boss

10007748-1

2/3





FIG. 3




FIG. 4

LOW THERMAL MASS HEATED FUSER

Roland Boss

10007748-1

3/3




FIG. 5




FIG. 6




FIG. 7